

Green Electronics Council

227 SW Pine Street, Suite 300 • Portland, OR 97204 • V: (503) 279-9382 • F: (503) 279-9381 • www.epeat.net

OUTCOMES REPORT EPEAT VERIFICATION ROUND PC-2018-03

1. Overview of Verification Round

PC-2018-03 included 65 Level 0 and 1 investigations on 9 criteria. The selected criteria were either those that lent themselves well to Level 0 investigations or those for which demonstration of conformance is difficult. All geographies and manufacturers with products active on the EPEAT Registry were eligible for inclusion in this Round. Criteria which were investigated during this Round included:

- 4.1.3.1- Required- Reporting on amount of mercury used in light sources
- 4.1.3.3- Optional- Elimination of intentionally added mercury used in light sources
- 4.3.1.1- Required- Identification of materials with special handling needs
- 4.4.1.1- Required- Availability of additional 3 year warranty or service agreement
- 4.5.2.1- Optional- Renewable energy accessory available
- 4.6.1.1- Required- Provision of product take back service
- 4.7.1.1- Required- Demonstration of corporate environmental policy consistent with ISO 14001
- 4.7.3.1- Required- Corporate report consistent with Performance Track or GRI
- 4.7.3.2- Optional- Corporate report based on GRI

Note: Criterion 4.5.2.2, Renewable energy accessory standard, was planned to be investigated during this round; however it was dropped from the round as no manufacturers were claiming it.


Criteria 4.4.1.1, 4.5.2.1, and 4.7.3.2 were investigated via Level 0 investigation. In a Level 0 investigation, an Auditor assesses Conformance to a criterion by examining publicly available information only – no products are obtained for inspection or testing, and the Manufacturer is not asked to submit documentation. If the publicly available information is inconclusive (i.e. was not available, could not be found from public sources, or did not provide enough details to determine conformance), the Auditor may be instructed to proceed with a Level 1 investigation. In this round, 15 Level 0 investigations were assigned, and 12 proceeded to Level 1 investigations following completion of the Level 0 portion of the round.


Criteria 4.1.3.1, 4.1.3.3, 4.3.1.1, 4.6.1.1, 4.7.1.1, and 4.7.3.1 were investigated via Level 1 investigation after completion of the Level 0 portion of the round. In a Level 1 investigation, an Auditor assesses Conformance to a criterion by examining information submitted by a Manufacturer. The Manufacturer is required to provide detailed and accurate information in a timely manner.

2. Summary of Outcomes

The following is a summary of Outcomes from this round:

- 65 investigations assigned
- 4 investigations cancelled
- 15 investigations at Level 0
- 12 Level 0 investigations Inconclusive and moved to Level 1
- 39 decisions of Conformance
- 22 decisions of Nonconformance





3. Key Lessons

Criterion 4.3.1.1 Required—Identification of materials with special handling needs

This criterion requires manufacturers to identify the presence and location of materials with special handling needs (typically, those that appear in the EU WEEE Directive). Manufacturers are advised to keep their disassembly reports for products up-to-date, and ensure that any materials submitted as evidence can demonstrate both the presence and location of such materials.

Criterion 4.6.1.1 Required—Provision of product take-back service

This is a complex criterion with many requirements to demonstrate conformance. Manufacturers should be able to identify any recyclers associated with the take back program and demonstrate a business relationship with them. Any costs to the consumer associated with the take back program should also be disclosed.

Criterion 4.7.1.1 Required—Demonstration of corporate environmental policy consistent with ISO 14001

This criterion requires the manufacturer to demonstrate that their written corporate environmental policy is consistent with all aspects of the requirements laid out in the environmental policy section of ISO 14001. Manufacturers should ensure that they are able demonstrate how their written environmental policy meets the requirements of the environmental policy section of ISO 14001.

3. General Message to Manufacturers

<u>Understanding documentation requirements for Verification Rounds:</u>

You can find more guidance and examples of conformance documents in the Conformity Sample Packets located in "Key Documents" under My Account. Go to epeat.net to log in.

Initial response to Auditors:

When contacted regarding participation in a Verification Round, Manufacturers should respond to the Auditor as soon as possible to let them know they are communicating with the correct person or to inform them of the correct contact. This also helps the Auditor know that the e-mail address is valid.

Conformance of products that may share similar traits and/or supply chains:

If a Non-Conformance is found for a particular criterion and product, Manufacturers should be prepared to determine if other products on the EPEAT Registry are similarly impacted due to use of similar materials and/or supply chains, and develop corrective action plans to address the future conformance of these other products.

4. Looking Forward

Plans for Future Verification Activities:

The EPEAT Program will begin verification to IEEE 1680.1 2018 in the first half of 2019.

Conformity Sample Packets:

This and all future Verification Rounds will be conducted according to the guidance provided in the Conformity Sample Packets posted on www.epeat.net under "Key Documents" in My Account.

Outcomes Report Page 3
EPEAT Verification Round PC-2018-03
December 2018

5. Investigations Table

| TABLE 1: Specific Non-Conformance Findings and Corrective Action Taken | | | | | | | | | |
|--|---------------------------------------|---------------|------------------------------------|-----------|----------------------|---|---|---|--|
| Participating Manufacturer | Product | Country | Product Type | Criterion | Required or Optional | Criterion Description | NC Finding Description | Corrective Action Taken | |
| Action S.A. | SIERRA 500X ES01 | Poland | Desktops | 4.7.3.2 | Optional | Corporate report based on GRI | Insufficient documentation to prove conformance | Criterion undeclared by Manufacturer. | |
| digital computer | Ascent Desktop - D- XXXX | Brazil | Desktops | 4.5.2.1 | Optional | Renewable energy accessory available | No documentation provided | Other - Description: Administrative error | |
| HP Inc. | ProDisplay P232 23-inch Monitor | Taiwan | Monitors | 4.5.2.1 | Optional | Renewable energy accessory available | No documentation provided | Other - Description: Manufacturer corrected registry declaration | |
| HP Inc. | 24w 23.8-inch Display | United States | Monitors | 4.4.1.1 | Required | Availability of additional 3 year warranty or service agreement | Insufficient documentation to prove conformance | Product archived by Manufacturer. | |
| Inida | M500 2000 IN500.01 | Lithuania | Desktops | 4.7.3.2 | Optional | Corporate report based on GRI | No documentation provided | Other - Description: Administrative error | |
| NTT System S.A. | NTT Business W 504M | Poland | Desktops | 4.4.1.1 | Required | Availability of additional 3 year warranty or service agreement | Insufficient documentation to prove conformance | If NC due to insufficient evidence, Manufacturer provided additional evidence to demonstrate conformance. | |
| Positivo Tecnologia S.A. | Positivo Master A2100 | Brazil | Integrated Desktop Computers | 4.7.3.2 | Optional | Corporate report based on GRI | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. | |
| Algoritmos Procesos y Disenos, S.A. | ALDA CE | Spain | Desktops | 4.7.1.1 | Required | Demonstration of corporate environmental policy consistent with ISO 14001 | Insufficient documentation to prove conformance | If NC due to insufficient evidence, Manufacturer provided additional evidence to demonstrate conformance. | |
| Arquimedes Automacao e Informatica Ltda | Corporativo A | Brazil | Desktops | 4.3.1.1 | Required | Identification of materials with special handling needs | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. | |

| TABLE 1: Specific Non-Conformance Findings and Corrective Action Taken | | | | | | | | | |
|--|-------------|---------------|-----------------|-----------|----------------------|--|---|--|--|
| Participating Manufacturer | Product | Country | Product Type | Criterion | Required or Optional | Criterion Description | NC Finding Description | Corrective Action Taken | |
| CIARA-TECH | ASUS UN45 | Canada | Desktops | 4.3.1.1 | Required | Identification of materials with special handling needs | Demonstrated non- conformance | Product archived by Manufacturer. | |
| Corporativo Lanix, S.A. de C.V | Neuron R II | Mexico | Notebooks | 4.1.3.3 | Optional | Elimination of intentionally added mercury used in light sources | No documentation provided | Other - Description: Manufacturer did not take corrective action, and CAB archived the product | |
| Corporativo Lanix, S.A. de C.V | LX900T | Mexico | Monitors | 4.7.3.1 | Required | Corporate report consistent with Performance Track or GRI | No documentation provided | Other - Description: Insufficient evidence was provided to re-establish conformance. CAB archived the Manufacturer's products. | |
| Dell, Inc. | XPS 13-9365 | Sweden | Notebooks | 4.3.1.1 | Required | Identification of materials with special handling needs | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. | |
| Durabook Americas Inc. | S15AB | United States | Notebooks | 4.7.3.1 | Required | Corporate report consistent with Performance Track or GRI | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. | |
| Howard Technology Solutions | H11AKB | United States | Desktops | 4.3.1.1 | Required | Identification of materials with special handling needs | Demonstrated non- conformance | Other - Description: Product was archived as a result of an earlier corrective action | |
| Komparsa UAB | S1700F | Latvia | Desktops | 4.7.3.1 | Required | Corporate report consistent with Performance Track or GRI | Insufficient documentation to prove conformance | If NC due to insufficient evidence, Manufacturer provided additional evidence to demonstrate conformance. | |
| Login Informatica | Login L4500 | Brazil | Desktops | 4.7.3.1 | Required | Corporate report consistent with Performance Track or GRI | Insufficient documentation to prove conformance | If NC due to insufficient evidence, Manufacturer provided additional evidence to demonstrate conformance. | |
| TH ALPLAST | S27 | Poland | Desktops | 4.7.3.1 | Required | Corporate report consistent with Performance Track or GRI | Insufficient documentation to prove conformance | Other - Description: Manufacturer did not take corrective action, and CAB archived all active products | |

| Participating Manufacturer | Product | Country | Product Type | Criterion | Required or Optional | Criterion Description | NC Finding Description | Corrective Action Taken |
|-------------------------------|-----------------------|---------------|-----------------|-----------|----------------------|---|---|---|
| Toshiba | Tecra X40-D PT472C | Canada | Notebooks | 4.3.1.1 | Required | Identification of materials with special handling needs | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. |
| TPV Technology Limited | E2475SWQE | Netherlands | Monitors | 4.6.1.1 | Required | Provision of product take back service | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. |
| Transource | MIR-Q900S | United States | Desktops | 4.6.1.1 | Required | Provision of product take back service | Insufficient documentation to prove conformance | If NC due to insufficient evidence, Manufacturer provided additional evidence to demonstrate conformance |
| ViewSonic Corporation | CDX5552 VS16172 | Canada | Monitors | 4.3.1.1 | Required | Identification of materials with special handling needs | Demonstrated non- conformance | If NC due to demonstrated non- conformance, Manufacturer provided evidence of changes made resulting in conformance. |

6. Background

To assure the credibility of the EPEAT Registry, verification of the claims by Participating Manufacturers are rigorous, independent and transparent. Verification is conducted according to policies and procedures described in documents provided on www.epeat.net. Manufacturers are given no forewarning that their products will be verified, and verification is performed based on the declarations as they are in the Registry at the time the Verification Round begins.

Investigations are performed by expert technical contractors called Auditors working for a Conformity Assurance Body approved by the Green Electronics Council (GEC). Auditors are free of conflicts of interest, and their recommended decisions are reviewed and finalized by a four-person panel of independent technical experts (called the Conformity Decision Panel) who are also contractors free of conflicts of interest. Decisions of conformity by the Conformity Decision Panel are made blind to the identity of the products and companies they are judging, based only on evidence collected and analyzed by Auditors. A serious consequence of receiving a Non-Conformance is that it is published publicly in an Outcomes Report, for purchasers, competitors, and others to see.

- In a Level 0 investigation, an Auditor assesses Conformance to a criterion by examining publicly available information only no products are obtained for inspection or testing, and the Manufacturer is not asked to submit documentation. If the publicly available information is inconclusive (i.e. was not available, could not be found from public sources, or did not provide enough details to determine conformance), the Auditor may be instructed to proceed with a Level 1 investigation.
- In a Level 1 investigation, an Auditor assess Conformance to a criterion by examining information submitted by a Manufacturer. The Manufacturer is required to provide detailed and accurate information in a timely manner.
- In Level 2 investigations, the Conformity Assurance Body obtains a product without the Manufacturer's knowledge or involvement, and has the product disassembled and inspected to assess conformance with one or more criteria.
- In Level 3 investigations, the Conformity Assurance Body obtains a product without the Manufacturer's knowledge or involvement, and has the product analytically tested to assess conformance with one or more criteria.

Manufacturers must correct Non-Conformances, either by bringing the product into Conformance, by un-declaring the criterion until Conformance is achieved, or by removing the product from the Registry. The Green Electronics Council also requires that Manufacturers examine other registered products to determine if their declarations should be corrected as well. If a Manufacturer corrects the Non-Conformance by un-declaring the criterion and the criterion is an optional criterion, they lose that point, and possibly the product drops a tier. If it is a required criterion, they must archive the product. If it is a required corporate criterion, they must archive all of their registered products.